# **UNDERCOVER LED KIT USER MANUAL**

CONTENTS

LIGHTHEAD x 2pcs

**EXTENSION CABLE** 

FLASHER & CABLE

FLANGE OPTION x 2pcs











## LIGHT ASSEMBLY INSTALLATION

- 1. Remove the Corner/Head/Tail light from vehicle.
- 2. Select location to mount lighthead.
- 3. Drill 1 inch diameter hole to the light assembly.
- 4. Insert lighthead into hole.
- 5. Apply silicone (user-supplied) for better fit.

WARNING: Do NOT cover heat sink with silicone. It may cause damage to the product and void warranty.

#### **OPERATIONS**


To +VDC (fuse @2A) for Color1 activation......RED -To Chassis Ground......BLACK To +VDC (fuse @2A) for Color2 activation.......WHITE For Synchronization & Flash Patterns.....YELLOW Connect YELLOW wires of all Kits together for synchronization \*All kits must be set at the same pattern

For Simultaneous or Split Flash (single head):

- 1. Apply +VDC to RED and YELLOW wires simultaneously to enter Mode selection; lighthead will display single flash.
- 2. Remove YELLOW wire from +VDC and momentarily apply to +VDC to change Mode: Mode1 = Simultaneous Flash, Color1 and Color2 LEDs flash together. Mode2 = Split Flash, Color1 LEDs alternate with Color2 LEDs.

Mode1 (Simultaneous Flash)			Head1	Head2	
(Suitable for Single-Color Heads)		Flash	Color1 Color2	Color1 Color2	
Flash Patterns #1~9	Color1 &2 flash together, Head1 alternate Head2	1st 2nd	on on off	off off on on	
Flash Patterns #10~17	Color1&2 flash together, Head1&2 flash together	1st 2nd	on on off off	on on off off	
Flash Pattern #18	Steady Half	1st 2nd	on on on	on on off	

Mode2 (Split Flash)			Head1	Head2
(Suitable for Split-Color Heads)		Flash	Color1 Color2	Color1 Color2
Flash Patterns #1~9	Color1 alternate Color2	1st 2nd	on off off on	off on off
Flash Patterns #10~17	Color1 flash together, Color2 flash together	1st 2nd	on off off on	on off off on
Flash Pattern #18	Steady Half	1st 2nd	on on off	on on off



For Flash Pattern change, momentarily apply +VDC to YELLOW wire: · once for next pattern


· quickly three times for reset

Flash Patterns					
1	Random	11	Double (all)		
2	Single (split)	12	Quad (all)		
3	Double (split)	13	Quint (all)		
4	Quad (split)	14	Mega (all)		
5	Quint (split)	15	Ultra (all)		
6	Mega (split)	16	Single-Quad (all)		
7	Ultra (split)	17	Single H/L (all)		
8	Single-Quad (split)	18	Steady Half		
9	Single H/L (split)	19	Steady All		
10	Single (all)				


NOTE: This unit may not be factory set at FP# 1.

## FLANGE MOUNT INSTALLATION (for kits with Flange option only)


1. Remove Original Base Plate from lighthead base.



2. Secure Flange Plate to lighthead base with screws.



- 3. Use mounting flange to mark wire and screws holes to drill.
- 4. Drill marked holes accordingly.
- 5. Insert lighthead pigtail into wire hole.
- 6. Place foam, lighthead, and flange in line with the mounting holes, and secure with supplied sheet metal screws.



WARNING: Make sure to use the foams when mounting lightheads.

### WIRING TO EXISTING STROBE CABLES

In this configuration, existing strobe extension cables are used to facilitate installation.

